

RECEIVED APR 2 1 1992

333 Pfingsten Road
Northbrook, Illinois 60062-2096
(708) 272-8800
FAX No. (708) 272-8129
MCI Mail No. 254-3343
Cable ULINC NORTHBROOK, IL
Telex No. 6502543343



April 6, 1992

Fiberlock Technologies, Inc.
Mr. Mark O'Connor
630 Putnam Ave.
P. O. Box 390432
Cambridge, MA 02139

Our Reference: R13770

Dear Mr. O'Connor:

This is in regard to your fax of March 17, 1992.

In Decemeber of 1991, Surface Burning Characteristic Tests were conducted on samples of your coating with the following results:

<u>Test No.</u>	<u>Flame Spread</u>	<u>Smoke Developed</u>
1	5.1	3.1
2	3.9	0.1

Base on the above test results, the following Surface Burning Characteristics Classification would be applicable for the coating:

Surface Burning Characteristics

Flame Spread	5
Smoke Developed	0

After reviewing the test data and Follow-Up Service Procedure R13770, it is our judgement that the above Classification could be extended to your "Fiberset FT" and "Fiberset PM" products based upon the similarity of formulation to the coating tested.

However, the only evidence of Surface Burning Characteristics Classification is the appearance of the UL Classification Marking on the product.